Qty:

Each

23

4 Um:

: FLOAT STEP ASSEMBLY RH (206/407)

: D2842042

: 02/10/2008

: N/A

: B

D2842 REV B

Date: User:

Monday, 22/09/2008 10:13:31 AM

Julie Lecocq

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

Estimate Number

: 42143A : 11775

P.O. Number

This Issue

Prsht Rev.

Written By

: 22/09/2008

: NC

First Issue Previous Run.

: 22/09/2008

Type

: 36966A

S.O. No. :

Checked & Approved By

Comment

: Est Rev:D

As Per Ecn 766 06-01-06 JLM

: LARGE FAB ASSY

Additional Product

Job Number:

Seq. #:

Machine Or Operation:

Description: Step Extrusion

1.0

2.0

D2622120C

Comment: Qty.:

1.0000 Each(s)/Unit

Total:

Part# D2622-120C Description Extrusion

4.0000 Each(s) Batch:

B39316

Check Material for any Dents or Defects

LARGE FAB 1

LARGE FABRICATION RESOURCE

Comment: LARGE FABRICATION RESOURCE 1

1-Cut D2842-1 using D2622 extrusion as per Dwg D2842

2-Drill D2842-1 using Jig DT8272 as per Dwg D2842

3-Deburr and bevel ends for welding

D2734

Step End Plate

08-11-12

3.0

2.0000 Each(s)/Unit Total:

8.0000 Each(s)

Comment: Qty.: 206 Step Endplate

Pick:

Qty Part Number 2 D2734

Description

End Cap

Dart Aeros	pace l	∟td
-------------------	--------	-----

		-								
W/O:			W	ORK ORDER CHANG	SES					
DATE	art No: PAR #:	OCEDURE CHA	ANGE 3		By Da		Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
-	TE STEP PI TE STE									
· · · · · · · · · · · · · · · · · · ·		.1								
· v										
Part No	:	PAR #:	Fault Cate	egory:	NCR:	Yes N	lo DQ /	A :	Date:	
				Disposition: QA: N/C Closed:						
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR)				
DATE	CTED	Description of NC			tion B		Verific	ation	Approval	Approval
DATE	SIEP		Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
			•							
										Tr. C.
الهجو بـ										
					Ţ					

Monday, 22/09/2008 10:13:31 AM Date: User: Julie Lecoca **Process Sheet Drawing Name:** FLOAT STEP ASSEMBLY RH (206/407) Customer: CU-DAR001 Dart Helicopters Services Part Number: D2842042 Job Number: 42143A Job Number: Seq. #: Description: **Machine Or Operation:** 4.0 D34591 Float Step Mounting Plate 2.0000 Each(s)/Unit Total: 8.0000 Each(s) Comment: Qty.: plate 37-346.=3L Batch: 3 D34593 5.0 2.0000 Each(s)/Unit Total: 8.0000 Each(s) Comment: Qty.: plate Batch: **B3778** LARGE FAB 6.0 Comment: LARGE FABRICATION RESOURCE 1 1-Weld one end cap and (2) lugs as per Dwg D2842 AL Rod Batch: MIO9 213 ap 08.11.13 2-Grind end cap weld flush QC9 7.0 Comment: VISUAL DING INSPECTION INSPECT WORK TO CURRENT STEF QC5 8.0 Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING RESOURCE #1 HAND FINISHING1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1

			,
D	A	space	1 4 4
1 12 PT	NOTO	chara	110
Uait	ACIU	SUGGE	LIM

Duit Aci	Ospace	LW								
W/O:			. W	ORK ORDER CHANG	SES					
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			·							
						•				
										[
									10	
Part No		PAR #:	Fault Cate	egory:	_ NCR	: Yes N	o DQ .	A:	Date: _	
	Re	solution:	Disposition	on:	QA:	N/C Clos	sed:		Date: _	
NCR:			WORK ORE	ER NON-CONFORM	ANCE	(NCR)				
DATE	OTED	Description of NC			tion B		Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date		ion C	Chief Eng	QC Inspector
		*								
				•						
								<i>-</i> 1		

Monday, 22/09/2008 10:13:31 AM Julie Lecocq **Process Sheet** Drawing Name: FLOAT STEP ASSEMBLY RH (206/407) Customer: CU-DAR001 Dart Helicopters Services Job Number: 42143A Part Number: D2842042 Job Number: Seq. #: **Machine Or Operation:** Description: INSPECT POWDER COAT/CHEMICAL CONVERSION QC3 10.0 POWDER COAT/CHEMICAL CONVERSION LARGE FABRICATION RESOURCE 1 LARGE FAB 11.0 Comment: LARGE FABRICATION RESOURCE 1 1-Remove alodine prior to welding. Weld end cap as per Dwg D2842. p 08.11.17 AL Rod Batch: M 164855 2-Grind end cap weld flush. QC9 VISUAL WELDING INSPECT 12.0 Comment: VISUAL WELDING INSPECTION INSPECT WORK TO CURRENT STEP 13.0 QC5 Comment: INSPECT WORK TO CURRENT STEP POWDER COATING POWDER COATING 14.0 Comment: POWDER COATING Touch up Alodine end cap and Powder Coat Gloss White (Ref. 4.3.5.1) as per QSI 005 4.3 START TIME: **OVEN TEMPERATURE:** FINISH TIME: INSPECT POWDER COAT/CHEMICAL CONVERSION 15.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 16.0 3.0000 Each(s)/Unit Total: 12.0000 Each(s) Comment: Qty.: Insert Pick: Description Batch **Qty Part Number** m 10695 NAS1329C3KB130Insert

Dart Aerospace L	Ltd
------------------	-----

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng /	Approval QC Inspector
							 	Prod Mgr	<u>'</u>
	:								
Part No		PAR #:	Fault Ca	tegory:	_ NCR: Yes	No DQ	A :	Date:	
	Resolution: Disposition:				_ QA: N/C C	osed:		Date:	
NCR:		V	VORK OR	DER NON-CONFORM	ANCE (NCF	R)			
DATE	STEP	Description of NC			ion B	Verific	ation	Approval	Approval
DAIL	SILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date		on C	Chief Eng	QC Inspector
						į			
			1						
							· · · · · · · · · · · · · · · · · · ·		
¥							·		
					-				*

Monday, 22/09/2008 10:13:31 AM Julie Lecocq . User: ` **Process Sheet** Drawing Name: FLOAT STEP ASSEMBLY RH (206/407) Customer: CU-DAR001 Dart Helicopters Services Job Number: 42143A Part Number: D2842042 Job Number: Seq. #: Description: Machine Or Operation: 17.0 MS27039C107 screw Comment: Qty.: 3.0000 Each(s)/Unit Total: 12.0000 Each(s) Pick: **Qty Part Number** Description MS27039C1-07 Screw NAS1515H3L 18.0 Comment: Qty.: 3.0000 Each(s)/Unit Total: 12.0000 Each(s) Pick: **Description Batch Qty Part Number** NAS1515H3L WASHER 19.0 AN960C10L Total: 12.0000 Each(s) Comment: Qty.: 3.0000 Each(s)/Unit Pick: **Qty Part Number** Description WASHER AN960C10L 20.0 HAND FINISHING1 Comment: FINISHING 1 1-Install inserts as per Dwg D2842 2-Wing Walk as per Dwg D2842 and QSI 005 4.1 INSPECT WORK TO CURRENT STEP 21.0 QC5 Comment: INSPECT TO CURRENT STEP PACKAGING RESOURCE #1 22.0 **PACKAGING**



Comment: PACKAGING RESOURCE #1 Identify and Stock

Location:



Page 4

Dart	Aeros	pace l	Ltd
------	-------	--------	-----

Duit Aci	Jopade	·								
W/O:			W	ORK ORDER CHANGE	S					
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
•										
Part No	•	PAR #:	Fault Cat	egory:	NCR: Yes	No DQ	A:	_ Date: _		
	Resolution:			on:	QA: N/C Cld	sed:		Date:		
NCR:		1	WORK OR	DER NON-CONFORMA	NCE (NCR)				
		Description of NC		Corrective Action Section		Verific	ation	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC Inspector	
								:		

User:

Monday, 22/09/2008 10:13:31 AM

Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT STEP ASSEMBLY RH (206/407)

Job Number: 42143A

Part Number: D2842042

Job Number:



Seq. #:

Machine Or Operation:

Description:

23.0

QC21

FINAL INSPECTION/W/O RELEASE

08/11/91

ECTION/W/O RELEASE

Job Completion




W/O:		WORK ORDER CHANGE	S	· · · · · · · · · · · · · · · · · · ·		- *	
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval ChiefÆng / Prod Mgr	Approval QC Inspector
						٦	
÷		**					
-							
						, ,	

上述了这种

Part No:		PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed:	Date:

NCR:		* · · · · · · · · · · · · · · · · · · ·	WORK OR	DER NON-CONFORMANC	E (NCR)			
		Description of NC		Corrective Action Section B		Verification	Approval	Approval
DATE	STEP	Section A		Initial Chief EngAction Description Chief EngSign & Date		Section C	Chief Eng	QC Inspector
	Ì							
						234	,	
							_	
				,				
a.	. 1		1		1	1	[1



WITHOUT NOTICE